

	<b>Release protocol</b> <b>for Standard-Device-Firmware</b> <b>SPS electronic</b>	Page 1 / 2
		Created: (Date/Name): 01.03.2021 / J. Scheu

<b>Firmware for: Series 18x5/6</b>
------------------------------------

**Notification list:**

Management GL:	Quality Assurance QS:
Development EW:	Shipping Audit SA:
Sales VT:	Service KD:
Marketing MK:	Calibration Lab KL:
Dokumentation DK:	Engineering EK:

<b>Changes to previous version : 1.7.1.2</b>  - Version tested: 1.7.1.8 -> Version released after bugfix: 1.7.1.9. - Fix checking of safety input HV and IS step, test stops now immediately in waiting for voltage if safety input is opened. Was waiting for 2s timeout before. - New function to set testpart directly after meas command for compatibility with DAT. - Fix problem in remote communication over serial that caused communication timeout. - Fix processing of every remote command in input buffer before start timer to prevent overflow. - Fix using passwords with "/" for ftp connection. - Cif modul support SMB2 attached to update package. - Fix CR result, save now the same value used to detect pass/failed. - Fix memory leak in S0 Step.
---

<b>New Version: 1.7.1.9</b>
-----------------------------

<b>Checklist</b>	OK	Tester Name/Datum
<b>1. Checklist A1:</b> Remark:	<input checked="" type="checkbox"/>	J. Surkala / F. Lienland 29.09.2021
<b>2. Checklist A2:</b> Remark: n.a.	<input checked="" type="checkbox"/>	J. Scheu

Created: (Date/Name):  
01.03.2021 / J. ScheuDocument:  
FO\_EW\_10.DOC**Firmware released:**Date: **22. Okt. 2021**

Name / Signature:

*Jan Scheu* 

<b>Action:</b>	<b>OK</b>	<b>Name / Date</b>
Update in list „Current Versions“:	<input checked="" type="checkbox"/>	<b>22. Okt. 2021</b>
New Firmware placed on server G:\Software\Firmware\...:	<input checked="" type="checkbox"/>	<b>22. Okt. 2021</b>
Forwarding new Firmware to supplier of affected parts:	<input checked="" type="checkbox"/>	<b>22. Okt. 2021</b>