Release notes of firmware update
V1.7.0.0 – Series 18x5

- Improved regulation and discharging in hot high voltage test method.
- Improved measurement value synchronization for better performance also with remote interface.
- Improved protocol dialog in remote mode for better remote performance.
- Fixed error that PW start button could not be set as safety contact.
- Fixed error that the SYST:HALT command could interrupt the communication under certain conditions.
- Added PW Offset feature in Global Test Settings.
- Added new status symbol for active Ethernet connection.